


# The State of New Mexico Rest Areas







Content:

07 | Section One | East and South East

- 08 | Anton Chico East Bound
- 09 | Anton Chico West Bound
- 10 | Blackwater Draw
- 11 | Glenrio Visitor Center
- 12 | Maljamar
- 13 | Mesa
- 14 | Pajarito East Bound
- 15 | Pajarito West Bound
- 16 | Rattlesnake Draw East Bound
- 17 | Rattlesnake Draw West Bound
- 18 | Waldrop

19 | Section Two | North and North East

- 20 | Ft. Union North Bound
- 21 | Ft. Union South Bound
- 22 | La Bajada Visitor Center
- 23 | Rio Grande Gorge Bridge
- 24 | Sierra Grande (U.S. 64)
- 26 | Thaxton North Bound
- 27 | Thaxton South Bound


28 | Section Three | South and South West

- 29 | Anthony
- 30 | Butterfield Trail
- 31 | Gage
- 32 | Ft. Craig North Bound
- 33 | Ft. Craig South Bound
- 34 | Ft. Seldon North Bound
- 35 | Ft. Seldon South Bound
- 36 | Las Cruces Overlook
- 37 | Lordsburg Visitor Center
- 38 | Walking Sands North Bound
- 39 | Walking Sands South Bound
- 40 | Yucca

41 | Section Four | West


- 42 | Acoma
- 43 | Manuelito Visitor Center

Interactive map





# Section One East and South East



- Anton Chico East Bound
- Anton Chico West Bound
- Blackwater Draw
- Glenrio
- Maljamar
- Mesa
- Pajarito East Bound
- Pajarito West Bound
- Rattlesnake Draw East Bound
- Rattlesnake Draw West Bound
- Waldrop







**Location:** Anton Chico East Bound  
**Number of parking spaces:** 27 Autos | 14 Trucks | 4 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table *(Family locked up)*  
**Women's Restroom:** 2 Stalls | 2 Sinks | 0 Baby-changing table *(Family locked up)*  
**Picnic Tables:** Yes **Number of picnic tables:** 7 **Picnic Shelters:** 6 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 marker  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 5  
**Comment:** Orange barrels and red cones situated around hazardous spots on ground.



**Location:** Anton Chico West Bound  
**Number of parking spaces:** 21 Autos | 23 Trucks | 3 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table  
**Women's Restroom:** 5 Stalls | 2 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 8 **Picnic Shelters:** 8 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 marker  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 5.5  
**Comment:** No water in sinks in men's and women's room due to high nitrate levels







**Location:** Blackwater Draw

**Number of parking spaces:** unmarked Autos | blocked Trucks | 0 Handicap

**ADA Restrooms:** Together

**Men's Restrooms:** locked and closed

**Women's Restroom:** locked and closed

**Picnic Tables:** Yes **Number of picnic tables:** 13 **Picnic Shelters:** 8 **Grills:** 5

**Lobby:** No

**Vending Machines:** No **With electrical outlets:** No

**Tourism Aspect:** None **Historical Markers or Tourism info:** 0 marker

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 0

**Comment:** Completely closed except for big lot trucks at pile of asphalt in far corner of big lot



**Location:** Glenrio Vistor Center

**Number of parking spaces:** 77 Autos | 53 Trucks | 16 Handicap

**ADA Restrooms:** Together and Family Room

**Men's Restrooms:** 6 Urinals | 4 Stalls | 6 Sinks | 2 Baby-changing table

**Women's Restroom:** 10 Stalls | 6 Sinks | 2 Baby-changing table

**Picnic Tables:** Yes **Number of picnic tables:** 2 **Picnic Shelters:** 0 **Grills:** 0


**Lobby:** Yes

**Vending Machines:** Yes **With electrical outlets:** Yes. Computer with free wifi

**Tourism Aspect:** Extensive **Historical Markers or Tourism info:** 1 marker

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8.5


**Comment:** Stickers on garbage cans, broken signs, paths to non-existent shelters. Graffiti on men's room mirrors and loose wires under sinks.







**Location:** Maljamar  
**Number of parking spaces:** 17 Autos | along curb Trucks | 4 Handicap  
**ADA Restrooms:** Not recorded  
**Men's Restrooms:** 1 Urinals | 2 Stalls | 1 Sinks | 0 Baby-changing table  
**Women's Restroom:** 2 Stalls | 1 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 3 **Picnic Shelters:** 4 **Grills:** 6  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** None  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8.5  
**Comment:** Nice, quaint and inviting.



**Location:** Mesa  
**Number of parking spaces:** 7 Autos | 5 Trucks | 2 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 1 Urinals | 2 Stalls | 0 Sinks | 0 Baby-changing table  
**Women's Restroom:** 3 Stalls | 0 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 5 **Picnic Shelters:** 5 **Grills:** 2  
**Lobby:** No  
**Vending Machines:** Yes **With electrical outlets:** No  
**Tourism Aspect:** 0 **Historical Markers or Tourism info:** 1 marker  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7  
**Comment:** Lots of space where shelters are. No sinks in men's restroom. Men's room soap dispenser locked-up.







**Location:** Pajarito East Bound  
**Number of parking spaces:** 18 Autos | 12 Trucks | 4 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 1 Baby-changing table  
**Women's Restroom:** 5 Stalls | 2 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 13 **Picnic Shelters:** 12 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 double sided  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 9  
**Comment:** closed



**Location:** Pajarito West Bound  
**Number of parking spaces:** 22 Autos | 14 Trucks | 5 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 1 Baby-changing table  
**Women's Restroom:** 5 Stalls | 2 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 8 **Picnic Shelters:** 7 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 double sided  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 9  
**Comment:** Open Fri-Sun. Leech lines/fields are problem. Drain too slow so have to shut down rest area so fields can dry.







**Location:** Rattlesnake Draw East Bound

**Number of parking spaces:** 17 Autos | 12 Trucks | 2 Handicap

**ADA Restrooms:** Together

**Men's Restrooms:** 2 Urinals | 4 Stalls | 2 Sinks | 0 Baby-changing table

**Women's Restroom:** 6 Stalls | 2 Sinks | 0 Baby-changing table

**Picnic Tables:** Yes **Number of picnic tables:** 10 **Picnic Shelters:** 10 **Grills:** 0

**Lobby:** No

**Vending Machines:** Yes **With electrical outlets:** No

**Tourism Aspect:** None **Historical Markers or Tourism info:** No

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7

**Comment:** Corral



**Location:** Rattlesnake Draw West Bound

**Number of parking spaces:** 16 Autos | 10 Trucks | 2 Handicap

**ADA Restrooms:** Together

**Men's Restrooms:** 2 Urinals | 4 Stalls | 2 Sinks | 0 Baby-changing table

**Women's Restroom:** 6 Stalls | 2 Sinks | 0 Baby-changing table

**Picnic Tables:** Yes **Number of picnic tables:** 12 **Picnic Shelters:** 9 **Grills:** 0

**Lobby:** No

**Vending Machines:** Yes **With electrical outlets:** No

**Tourism Aspect:** None **Historical Markers or Tourism info:** None

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7

**Comment:** Spigot by picnic shelter is broken. Can't water grass. There's a small livestock corral.








**Location:** Waldrop  
**Number of parking spaces:** 13 Autos | 5 Trucks | 2 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 1 Urinals | 2 Stalls | 1 Sinks | 0 Baby-changing table  
**Women's Restroom:** 2 Stalls | 1 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 7 **Picnic Shelters:** 4 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 marker  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8.5  
**Comment:** Trees are old and liable to fall over from strong winds. Individual solar panel is loose and twists in wind.



# Section Two North and North East



- Ft. Union North Bound
- Ft. Union South Bound
- La Bajada
- Rio Grande Gorge Bridge
- Sierra Grande (U.S. 64)
- Thaxton North Bound
- Thaxton South Bound





**Location:** Ft. Union North Bound  
**Number of parking spaces:** 19 Autos | 8 Trucks | 3 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table  
**Women's Restroom:** 5 Stalls | 2 Sinks | 1 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 5 **Picnic Shelters:** 5 **Grills:** 5  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 marker  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8  
**Comment:** Graffiti on men's room mirrors and stickers on heater.



**Location:** Ft. Union South Bound  
**Number of parking spaces:** 19 Autos | 7 along the curb Trucks | 3 Handicap  
**ADA Restrooms:** Not specified  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 1 Baby-changing table  
**Women's Restroom:** Not specified  
**Picnic Tables:** Yes **Number of picnic tables:** 6 **Picnic Shelters:** 5 **Grills:** 5  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Small museum locked up. **Historical Markers or Tourism info:** 2 markers  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7  
**Comment:** Graffiti on men's room mirrors and stalls. Stickers on heater. Graffiti on women's mirror.







**Location:** La Bajada  
**Number of parking spaces:** 26 Autos | 14 Trucks | 3 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 2 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table  
**Women's Restroom:** 3 Stalls | 2 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 11 **Picnic Shelters:** 8 **Grills:** 6  
**Lobby:** No  
**Vending Machines:** Yes **With electrical outlets:** Yes  
**Tourism Aspect:** Good **Historical Markers or Tourism info:** 13 markers and 6 double sided  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7  
**Comment:** Graffiti in men's room. Two dog walk areas. Stucco job started but needs finishing. Tile in men's room falling on drain. Floor is loose.



**Location:** Rio Grande Gorge Bridge  
**Number of parking spaces:** 22 Autos | RVs park along edge of the road | 5 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 2 Urinals | 2 Stalls | 1 Sinks | 0 Baby-changing table  
**Women's Restroom:** 2 Stalls | 1 Sinks | 1 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 9 **Picnic Shelters:** 8 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Extraordinary view **Historical Markers or Tourism info:** None at rest area perhaps down the road.  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 9.5  
**Comment:** Vendors tell me cleaning crew does a great job. Landscaping looks good. Picnic areas are clean. Restrooms are very clean.







**Location:** Sierra Grande (U.S. 64)  
**Number of parking spaces:** 26 Autos | Large unmarked areas | 3 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 1 Urinals | 2 Stalls | 2 Sinks | 1 Baby-changing table  
**Women's Restroom:** 3 Stalls | 2 Sinks | 1 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 6 **Picnic Shelters:** 6 **Grills:** 2  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Sign boards **Historical Markers or Tourism info:** 2 markers  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8  
**Comment:** Modern facilities. Separate restroom and family restroom. Shelters are old and wood is very weathered.



**Location:** Thaxton North Bound  
**Number of parking spaces:** 34 Autos | curbside Trucks | 3 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table  
**Women's Restroom:** 5 Stalls | 2 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 6 **Picnic Shelters:** 5 **Grills:** 1  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Sign boards **Historical Markers or Tourism info:** Yes  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 9  
**Comment:** Very clean. Contractor takes pride in their area.








**Location:** Thaxton South Bound  
**Number of parking spaces:** 22 Autos | spaces to park along the carb | 3 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table  
**Women's Restroom:** 5 Stalls | 2 Sinks | 1 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 5 **Picnic Shelters:** 5 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Sign boards **Historical Markers or Tourism info:** Yes  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 9  
**Comment:** Very clean.



# Section Three

## South and South West



- Anthony
- Butterfield Trail
- Gage
- Ft. Craig North Bound
- Ft. Craig South Bound
- Ft. Seldon North Bound
- Ft. Seldon South Bound
- Las Cruces Overlook
- Lordsburg
- Walking Sands North Bound
- Walking Sands South Bound
- Yucca





**Location:** Anthony  
**Number of parking spaces:** 9 Autos | 17 Trucks | 4 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 2 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table  
**Women's Restroom:** 3 Stalls | 2 Sinks | 2 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 18 **Picnic Shelters:** 18 **Grills:** 0  
**Lobby:** No. Lobby closed for three years. Info is outside.  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Non existent **Historical Markers or Tourism info:** 3 markers  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7  
**Comment:** Horse corral. Fountain motor burned out.



**Location:** Butterfield Trail  
**Number of parking spaces:** 8 Autos | curbside Trucks | 2 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 1 Urinals | 1 Stalls | 1 Sinks | 0 Baby-changing table | 1 of each in ADA  
**Women's Restroom:** 2 Stalls | 1 Sink | 0 Baby-changing table | 2 ADA stalls | 2 ADA sinks  
**Picnic Tables:** Yes **Number of picnic tables:** 4 **Picnic Shelters:** 4 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Limited **Historical Markers or Tourism info:** 1 marker  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 9  
**Comment:** ADA restrooms are modern otherwise restrooms are old. Landscaping is very nice.







**Location:** Gage (West bound I-10)

**Number of parking spaces:** 13 Autos | spaces to park along the carb | 5 Handicap

**ADA Restrooms:** Together and separate. Each restroom has ADA stalls.

**Men's Restrooms:** 2 Urinals | 1 Stalls | 2 Sinks | 0 Baby-changing table | 2 ADA urinals and stalls | 3 ADA sinks

**Women's Restroom:** 4 Stalls | 2 Sinks | 1 Baby-changing table | 3 ADA stalls and 2 sinks

**Picnic Tables:** Yes **Number of picnic tables:** 10 **Picnic Shelters:** 10 **Grills:** 0

**Lobby:** No

**Vending Machines:** No **With electrical outlets:** No

**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 marker

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8.5

**Comment:** Nice landscaping. Shelters are very spread out.



**Location:** Ft. Craig North Bound

**Number of parking spaces:** 34 Autos | curbside Trucks | 3 Handicap

**ADA Restrooms:** Together

**Men's Restrooms:** 3 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table

**Women's Restroom:** 5 Stalls | 2 Sinks | 0 Baby-changing table

**Picnic Tables:** Yes **Number of picnic tables:** 6 **Picnic Shelters:** 5 **Grills:** 1

**Lobby:** No

**Vending Machines:** No **With electrical outlets:** No

**Tourism Aspect:** None **Historical Markers or Tourism info:** 1 marker

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8.5

**Comment:** Nice landscaping. Shelters are very spread out.







**Location:** Ft. Craig South Bound

**Number of parking spaces:** 16 Autos | 2 spaces to park along the carb for Trucks | 2 Handicap

**ADA Restrooms:** Together and separate

**Men's Restrooms:** 2 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table | 2 ADA urinals and 1 stall | 2 ADA sinks

**Women's Restroom:** 5 Stalls | 2 Sinks | 1 Baby-changing table | 3 ADA and 2 ADA sinks

**Picnic Tables:** Yes **Number of picnic tables:** 8 **Picnic Shelters:** 8 **Grills:** 7

**Lobby:** Yes

**Vending Machines:** No **With electrical outlets:** No

**Tourism Aspect:** Map in lobby **Historical Markers or Tourism info:** 3 markers

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7.5

**Comment:** Water fountain in lobby is out of order. Graffiti on men's room mirror.



**Location:** Ft. Selden North Bound

**Number of parking spaces:** 21 Autos | 7 Trucks | 5 Handicap

**ADA Restrooms:** Together and separate

**Men's Restrooms:** 2 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table | 1 ADA urinal 2 stalls and 1 sink

**Women's Restroom:** 3 Stalls | 2 Sinks | 0 Baby-changing table | 3 ADA stalls and 1 ADA sink

**Picnic Tables:** Yes **Number of picnic tables:** 4 **Picnic Shelters:** 5 **Grills:** 0

**Lobby:** No

**Vending Machines:** No **With electrical outlets:** No

**Tourism Aspect:** None **Historical Markers or Tourism info:** 2 markers

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7

**Comment:**








**Location:** Ft. Selden South Bound  
**Number of parking spaces:** 22 Autos | 5 Trucks | 5 Handicap  
**ADA Restrooms:** Together and Separate  
**Men's Restrooms:** 2 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table | 1 ADA urinal 2 ADA stalls and 1 ADA sink  
**Women's Restroom:** 3 Stalls | 2 Sinks | 1 Baby-changing table | 3 ADA stalls 1 ADA sink  
**Picnic Tables:** Yes **Number of picnic tables:** 4 **Picnic Shelters:** 5 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** None **Historical Markers or Tourism info:** 3 markers  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8  
**Comment:** Graffiti in men's restroom on mirrors and walls. Outside graffiti as well.



**Location:** Las Cruces Overlook  
**Number of parking spaces:** 15 Autos | 14 Trucks | 3 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 1 Urinal | 3 Stalls | 2 Sinks | 0 Baby-changing table | 1 ADA urinal 2 ADA stalls and 2 ADA sinks  
**Women's Restroom:** 4 Stalls | 2 Sinks | 0 Baby-changing table | 3 ADA stalls and 2 ADA sinks  
**Picnic Tables:** Yes **Number of picnic tables:** 5 **Picnic Shelters:** 7 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** The View **Historical Markers or Tourism info:** 0 markers  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 9  
**Comment:** Very nice and clean area. One old restroom and one modern restroom.







**Location:** Lordsburg  
**Number of parking spaces:** 32 Autos | 10 Trucks | 4 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 5 Urinals | 4 Stalls | 4 Sinks | 0 Baby-changing table  
**Women's Restroom:** 9 Stalls | 4 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 12 **Picnic Shelters:** 6 **Grills:** 2  
**Lobby:** Yes  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Extensive **Historical Markers or Tourism info:** Several  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8.5  
**Comment:** Lobby full of tourism info. Restrooms are dark. Nice grounds.



**Location:** Walking Sands North Bound  
**Number of parking spaces:** 11 Autos | 8 Trucks | 2 Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 1 Urinal | 2 Stalls | 2 Sinks | 0 Baby-changing table | 2 ADA urinals 2 ADA stalls and 2 ADA sinks  
**Women's Restroom:** 3 Stalls | 2 Sinks | 0 Baby-changing table | 4 ADA stalls and 2 ADA sinks  
**Picnic Tables:** Yes **Number of picnic tables:** 20 **Picnic Shelters:** 10 **Grills:** 0  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Limited **Historical Markers or Tourism info:** 2 markers  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 7.5  
**Comment:** ADA water fountain outside doesn't work. Exterior of building is weathered.







**Location:** Walking Sands South Bound

**Number of parking spaces:** 15 Autos | 8 Trucks | 2 Handicap

**ADA Restrooms:** Together

**Men's Restrooms:** 2 Urinals | 2 Stalls | 2 Sinks | 0 Baby-changing table | 1 ADA urinal 2 ADA stalls and 2 ADA sinks

**Women's Restroom:** 4 Stalls | 2 Sinks | 0 Baby-changing table | 3 ADA stalls 2 ADA sinks

**Picnic Tables:** Yes **Number of picnic tables:** 18 **Picnic Shelters:** 10 **Grills:** 0


**Lobby:** No

**Vending Machines:** No **With electrical outlets:** No

**Tourism Aspect:** Limited **Historical Markers or Tourism info:** 3 markers

**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8

**Comment:** Usual graffiti on men's room mirrors. Toilets work on pressure.



**Location:** Yucca

**Number of parking spaces:** 20 Autos | curbside Trucks | 3 Handicap

**ADA Restrooms:** Together and separate

**Men's Restrooms:** 2 Urinals | 2 Stalls | 1 Sinks | 0 Baby-changing table | 2 ADA urinals 2 ADA stalls and 1 ADA sink

**Women's Restroom:** 3 Stalls | 1 Sinks | 0 Baby-changing table | 4 ADA stalls 2 ADA sinks

**Picnic Tables:** Yes **Number of picnic tables:** 10 **Picnic Shelters:** 10 **Grills:** 0

**Lobby:** No

**Vending Machines:** No **With electrical outlets:** No

**Tourism Aspect:** Old map **Historical Markers or Tourism info:** 1 marker


**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8

**Comment:** Just like the restroom at Gage rest area





# Section Four West



Acomita  
Manuelito



**Location:** Acomita (open 7:30–2:30 p.m.)  
**Number of parking spaces:** 116 Autos | Trucks share main lot | 3 Handicap  
**ADA Restrooms:** Together  
**2 Men’s Restrooms (one closed):** 2 Urinals | 4 Stalls | 1 Sinks | 0 Baby-changing table  
**2 Women’s Restrooms (one closed):** 6 Stalls | 2 Sinks | 0 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 20 **Picnic Shelters:** 20 **Grills:** 20  
**Lobby:** No  
**Vending Machines:** No **With electrical outlets:** No  
**Tourism Aspect:** Limited **Historical Markers or Tourism info:** 2 historic markers  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8  
**Comment:** Nice open space. It’s a chore to get to rest area—lots of traffic circles.







**Location:** Manuelito  
**Number of parking spaces:** TBD Autos | TBD Trucks | TBD Handicap  
**ADA Restrooms:** Together  
**Men's Restrooms:** 3 Urinals | 3 Stalls | 3 Sinks | 1 Baby-changing table  
**Women's Restroom:** 5 Stalls | 3 Sinks | 1 Baby-changing table  
**Picnic Tables:** Yes **Number of picnic tables:** 3 **Picnic Shelters:** 3 **Grills:** 3  
**Lobby:** Yes  
**Vending Machines:** Yes **With electrical outlets:** Yes  
**Tourism Aspect:** Yes **Historical Markers or Tourism info:** Yes. Route 66  
**Overall Condition (1-10, 1 is the worst and 10 is the best):** 8  
**Comment:** Currently closed for wastewater repairs. Parking lot repaired when complete.





